

Tackle your AAA

Louise Allen/Joanna Mason

Newborn Screening and Biochemical Genetics

Birmingham Children's Hospital



So what do we mean by *tackle*?

make determined efforts to deal with
(a problem or difficult task)



synonyms:

get to grips with, apply oneself to, address oneself to, [address](#), set about, go about, get to work at, take forward, busy oneself with, set one's hand to, grapple with, [approach](#), take on, attend to, see to, throw oneself into, try to solve, try to deal with, try to cope with, try to sort out!



Meet Jekyll and Hyde

- Autosampler, Biochrom 30+ amino acid analyser, PC with instrument control software + EZ Chrom Elite integration software



Our Biochrom 30 plus'

Jekyll and Hyde – named due to their slightly *unpredictable* nature



(And it's our local pub just across the road.....)




Briefly – How does it work?

- Sample prep – 1:1 with IS, containing deproteinising reagent SSA
- ?filter sample
- Plasma, CSF, urine
- Continuous flow cation-exchange.
- Lithium citrate buffers varying pH, ionic strength
- Accurately controlled temperature of the column
- Column resin – small beads of polystyrene with –ve charge
- Amino acids introduced at low pH – net positive charge
- Basic – most strongly bound, acidic least
- Separation is due primarily to differences in the pKA of the amino acids.
- Follows the general order: acidic, neutral, basic.
- Effluent that comes off the column mixed with the ninhydrin – passed through reaction coil at high temperature



- Ninhydrin reacts with the amino acids to form coloured compounds.
- Amount of coloured compound - directly proportional to the quantity of amino acid.
- The light absorption is measured at two wavelengths 570nm (purple) and 440nm (yellow)



Maintenance

Daily/Weekly

- Consumable levels (buffers, wash solutions) and waste

Monthly



- Isopropanol wash – reaction coil and back pressure valves
- Ninhydrin filter
- Reboot PC



Now it's your turn.....! Get ready

Audience participation section







Typical Lamp failure

- Electrical baseline noise
 - Spikes caused by filament collapsing
-
- Replace lamp
 - Other sources of baseline noise – flow-cell may require cleaning







Actually... Another Lamp failure

- Poor defined peaks ? Column fail, some spiking
- Trace sent to Biochrom
- Engineer visit

- Replace lamp
- Work through the obvious trouble-shooting first (lamp had only recently been replaced)







Column heating peltier failure

- Significant change to peak retention times
- Check that the column temperature increases and decreases when changed on Biosys instrument control
- check that both Peltier elements are heating
- Replace peltiers (Engineer visit)





baseline hasn't started at the correct position



this could be caused by:-

- 1) the Ninhydrin pump not coming on for the last two steps of the Biosys program so then the mixture of Buffer and Ninhydrin isn't correct so the baselines on both channels start near to zero .
- 2) the baseline reset hasn't happened

Solutions

- shut everything down and wait for 10 minutes and then turn everything back on
- run a regeneration program and then run a blank (loading buffer) and make sure the chromatography shows the starting points are 200mv for the 570nm channel and 100 mv for the 440nm channel.
- Also check chromatography display options are set correctly I.E. Auto scale







Resin contamination

- Distorted peaks
 - Poor separation
 - Exaggerated valleys
 - Headspace issue – affects separation at front of chromatography e.g up until Gly/Ala region
 - High buffer pressure errors (early stage column failure)
-
- Reverse flush the analytical column (instructions available from Biochrom)
 - Check head space and top up resin
 - replace column and clean







Undeproteinised sample

- Make sure all samples are pre-treated correctly!
 - Can try running Buffer 6 through
-
- Column required resin clean





Reaction coil heating failure

-Just seeing the buffer trace

- replace reaction coil (replaced in house)



Other errors

- Low buffer/ninhydrin pressure:-
 - ensure reservoirs are not empty
 - Ninhydrin filter changed – air in system?
- High ninhydrin pressure:-
 - Ninhydrin flow rate too high – program accidentally altered with flow rate increased for one step



Summary

- Low maintenance analyser
 - Generally very reliable
 - Always helpful advice from Biochrom
-
- Balance between the speed of the analysis and quality of trace
 - Volume of work
 - Consumable dependant – good stocks
 - Look for the obvious!

